

SE-100 SURFACE CRACK INDICATOR

**BALANCE ON MATERIAL
(LED WILL DISPLAY GREEN)**



**REACH TO THE DEFECT
(LED BECAME RED AND HORN ALARM)**



SE-100 SURFACE CRACK INDICATOR IS AN EDDY CURRENT TECHNIQUE FOR DETECTING FATIGUE CRACK IN FREEOUS WELD OR ROW MATERIAL. THIS INSTRUMENT GREATLY REDUCED THE COST AND TIME THAN ALTERNATIVE TECHNIQUES THAT REQUIRE PAINT OR OIL REMOVAL.



Scanning Weld Cap



Scanning Weld Toe and HAZ

RFS

Russell Fraser Sales Pty Ltd

Unit 8/29 Waratah St
Kirrawee NSW 2232

Ph: (02) 9545 4433

Fax: (02) 9545 4218

e-mail rfs@rfsales.com.au

web: www.rfsales.com.au

ABN: 79 074 258 549